



(inset)  
 (inset)  
 start  
 Date

		4708 Handheld Blower SPD		0880014002_SPD	
		4708 直流吹风机售后爆炸图			
		Exploded View		VERSION	C
				SCALE	IMP DEGREE
①	add The number 26 Core Nozzle Assembly (2825500082)	Designed by	朱广前	SHEET	1/1
c	更改通知单号: 000000857	Checked by	严荣军		
②	The number 12 Core Nozzle Assembly (2825500082) is replaced by Spray Nozzle Assembly (2825510002)	Approved by			
b	更改通知单号: 00000365R2	Effective Date	2018-07-18		
Revise	Core	Revision note			

**Repair Parts\_G3 580CFM Leaf Blower\_4708(LB5800E)**

<b>Model No.</b>	<b>LB5800E</b>
<b>Art. No.</b>	<b>0380052004</b>

<b>Index No.</b>	<b>Service Part No.</b>	<b>Description</b>		<b>QTY in machine</b>
1	2825155001	Handle Set		1.0
2	5620176002	Screw With Washer		2.0
3	3129005001	Switch Trigger		1.0
4	3660088003	Knob-reset Spring		2.0
5	3129004001	Boost Button		1.0
6	3128994001	Fan Baffle		1.0
7	5650519001	Rubber Gasket		4.0
8	3680196001	Magnet Ring		1.0
9	2826084001	Ducted Set		1.0
10	2825302001	Blow Tube ASSY		1.0
11		Anti-Static Bar	Acessory	1.0
12		Spread Nozzle Assembly	Acessory	1.0
13	5610294001	Tapping Screw		15.0
14		Harness	Acessory	1.0
15	2825680001	Bottom Support ASSY		1.0
16	5610021004	Tapping Screw		1.0
17	3650142001	Anti-Static Bar		1.0

18	3660614001	Compression Spring			1.0
19	3128266001	Lever			1.0
20	3127497001	Power Pack Button			1.0
21	3127498001	Power Pack Button			1.0
22	3660013003	Spring1			1.0
23	3129127001	Switch Box			1.0
24	2830399001	Electric Assembly			1.0
25	3706375001	Hook			1.0
26		Cone Nozzle Assembly	Accessory		1.0